ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0626, W0673, W0679, W0683, W0681, W0685, W0675	1st Crs, NA	Bhadrappa layout
Segment No.	**Total Length (m)**	
8/C-W0626/S020604	268.02	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	79.37	77.576037	13.048530	77.576768	13.048527	RI-S62	W0683
2	91.76	77.576505	13.048563	77.576561	13.049391	W0626	SWD
3	96.89	77.576198	13.048563	77.576269	13.049436	W0626	SWD

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Asphalting to roads in Bhadrappa layout in ward no 08 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	2000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Asphalting to roads in Bhadrappa layout in ward no 08 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	008-15-000039
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/53/2016-17	15/06/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
15/06/2016	14/06/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.NARASIMHA RAJU		0.00
Phone No.	**E-Mail ID**	

48083246

Field Inspection Details

Number of Trees	Any Other Information	Name
6		Srinivasa Murthy
Date of Inspection	**Remarks**	
26/07/2016	completed	

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0626, W0673, W0679, W0683,

ಯಲಹಂಕ ವಲಯ, ಬಿ.ಬಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು - 560092

Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	26/07/2016	25/08/2016	COMPLETED
SE	VASU K M	26/07/2016	25/08/2016	COMPLETED
EE	YARAPPA REDDY	26/07/2016	25/08/2016	COMPLETED
AEE	SHIVAKUMAR	26/07/2016	25/08/2016	COMPLETED
AE	SRINIVASA MURTHY	26/07/2016	25/08/2016	COMPLETED
AE	SRINIVASA MURTHY	26/07/2016	25/08/2016	COMPLETED

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೊಡಿಗೆಹಳ್ಳಿ ಉಪವಿಭಾಗ
ಯಲಹಂಕ ವಲಯ, ಬಿ.ಬಿ.ಎಂ.ಪ
ಬೆಂಗಳೂರು - 560092

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0626, W0673, W0679, W0683,